


INSTALLED 11/77

PLUMBING CONT: J. FLEISHMAN
ELEC CONT: THOMPSON ELEC
BUILDING INSP: FEENEY

NOTE: HEADROOM IS CLOSE AND CORE WILL NEED TO BE TIPPED TO GET OUT OF THE UNIT. OWNER DID NOT INSTALL VENT WITHIN 1' OF THE UNIT. IF THERE IS A PROBLEM WITH THE ALARM THEN HE WILL HAVE TO CORRECT IT.



NOTE: OWNER WILL NEED SOME CLEANDUTS IN THE 3" WASTE LINE, NOT THE WAY I WOULD LIKE IT DONE BUT TO PULL EVERYTHING APART NOW COULD CREATE A HARDSHIP.

REVISIONS	<i>GRINDER PUMP SKETCH</i>	TOWN OF GROTON WPCD GARY CT, GROTON
	ADDRESS: 66 RIVERVIEW AVE	
	NOANK	
DWG: RIVERV66	OWNER: JOHN & PAT RATHBUN	